

Inspection Photos
Operator: Simcoe
API: 067-07843
Date: 3/15/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the debris stored on the well pad, needs to be removed and properly stored or disposed of offsite.



Photo 3. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with intermediate wheatgrass, rubber rabbitbrush, sand dropseed, and western wheatgrass.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, yucca, mountain mahogany, and James galleta.