

Inspection Photos
Operator: Simcoe
API: 067-06340
Date: 3/15/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with western wheatgrass, sand dropseed, and rubber rabbitbrush.



Photo 3. View of the southern fill slope from the southeastern corner facing westward.



Photo 4. View of reference area comprised of rubber rabbitbrush and sagebrush shrubland with James galleta, blue grama, and sand dropseed in the understory.