

Inspection Photos

March 15, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335445

Location Name: HERRERA-66S92W /20NESE

Inspection Document #: 702800032

Garfield County, CO

NESE Section 20 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: HERRERA-66S92W /20NESE
Location ID: 335445



Photo 1. Photo taken from the southwest of the Location facing east shows an overview of the Location.

Inspection Photos
Location Name: HERRERA-66S92W /20NESE
Location ID: 335445



Photo 2. Photo taken from the southeastern production area facing west shows rutting occurring on the pad.

Inspection Photos
Location Name: HERRERA-66S92W /20NESE
Location ID: 335445



Photo 3. Photo taken from the center of the Location facing east shows undesirable plant species/weeds established on Location.



Photo 4. Photo taken from the center of the Location facing southeast shows undesirable plant species/weeds established on Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800032

Inspection Photos

Location Name: HERRERA-66S92W /20NESE

Location ID: 335445



Photo 5. Photo taken from the north of the Location facing north shows undesirable plant species/weed debris accumulating in production areas.



Photo 6. Photo taken from the east of the Location facing south shows undesirable plant species/weed debris accumulating along fencelines of the Location.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800032

Inspection Photos
Location Name: HERRERA-66S92W /20NESE
Location ID: 335445



Photo 7. Photo taken from the production area facing northeast shows undesirable plant species/weed debris accumulating in production areas.



Photo 8. Photo taken from the separator equipment facing southeast shows undesirable plant species/weed debris accumulating in production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800032

Inspection Photos
Location Name: HERRERA-66S92W /20NESE
Location ID: 335445



Photo 9. Photo taken from the north of the Location shows interim areas covered in snow. A follow up inspection is necessary to properly assess interim reclamation and stormwater management when snow is not present.