

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402988012

Receive Date:

03/17/2022

Report taken by:

CHRIS CANFIELD

Site Investigation and Remediation Workplan (Initial Form)

This form shall be submitted to the Director for approval prior to the initiation of site investigation and remediation activities. However, this shall not preclude the Operator from taking immediate action to protect public health or safety, the environment, wildlife, or livestock.

This Form 27 describes site conditions as currently understood by the Operator; approval of this Form 27 by COGCC is based on the site conditions accurately described herein; any changes in site conditions identified during or subsequent to the performance of the approved workplan may necessitate additional investigation or remediation which shall be described on a supplemental Form 27. This Form 27 is intended to provide basic information regarding the proposed site investigation and remediation actions, but the workplan may be more fully described in attached documentation.

Closure request is not available for an Initial Site Investigation and Remediation Workplan.

OPERATOR INFORMATION

Name of Operator: <u>GREAT WESTERN OPERATING COMPANY LLC</u>	Operator No: <u>10110</u>	Phone Numbers
Address: <u>1001 17TH STREET #2000</u>		Phone: <u>(720) 595-2132</u>
City: <u>DENVER</u>	State: <u>CO</u>	Zip: <u>80202</u>
Contact Person: <u>Jason Davidson</u>	Email: <u>j davidson@gwp.com</u>	Mobile: <u>()</u>

PROJECT, PURPOSE & SITE INFORMATION

PROJECT INFORMATION

Remediation Project #: 22476 Initial Form 27 Document #: 402988012

PURPOSE INFORMATION

- ☐ Rule 913.c.(1): Pit or Cuttings Trench closure.
- ☐ Rule 913.c.(2): Buried or partially buried vessel closure, which will be by removal.
- ☐ Rule 913.c.(3): Remediation of Spill and Releases pursuant to Rule 912.
- ☐ Rule 913.c.(4): Land treatment of Oily Waste pursuant to Rule 905.e.
- ☐ Rule 913.c.(5): Closure of Centralized E&P Waste Management Facilities pursuant to Rule 907.h.
- ☐ Rule 913.c.(6): Remediation of impacted Groundwater pursuant to Rule 915.e.(3).D, and the contaminant concentrations in Table 915-1.
- ☐ Rule 913.c.(7): Investigation and remediation of natural gas in soil or Groundwater.
- ☐ Rule 913.c.(8): When requested by the Director due to any potential risk to soil, Groundwater, or surface water.
- ☒ Rule 913.c.(9): Decommissioning of Oil and Gas Facilities.
- ☐ Rule 913.g: Changes of Operator.
- ☐ Rule 915.b: Request to leave elevated inorganics in situ.
- ☐ Other: _____

SITE INFORMATION

☐ Yes ☐ Multiple Facilities

Facility Type: <u>WELL</u>	Facility ID: _____	API #: <u>001-07649</u>	County Name: <u>ADAMS</u>
Facility Name: <u>GRANT PROPERTIES LTD. 1</u>		Latitude: <u>39.908060</u>	Longitude: <u>-104.142760</u>
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENW</u>	Sec: <u>6</u>	Twp: <u>2S</u>	Range: <u>60W</u>
Meridian: <u>6</u>		Sensitive Area? <u>No</u>	
Facility Type: <u>LOCATION</u>	Facility ID: <u>320008</u>	API #: _____	County Name: <u>ADAMS</u>
Facility Name: <u>GGREAT WESTERN GRANT PROP</u>		Latitude: <u>39.908060</u>	Longitude: <u>-104.142760</u>
** correct Lat/Long if needed: Latitude: _____		Longitude: _____	
QtrQtr: <u>SENW</u>	Sec: <u>6</u>	Twp: <u>2S</u>	Range: <u>60W</u>
Meridian: <u>6</u>		Sensitive Area? <u>No</u>	

SITE CONDITIONS

General soil type - USCS Classifications SM

Most Sensitive Adjacent Land Use Agricultural

Is domestic water well within 1/4 mile? No

Is surface water within 1/4 mile? No

Is groundwater less than 20 feet below ground surface? No

Other Potential Receptors within 1/4 mile

The Grant Properties 1 tank battery is surrounded by agricultural/cultivated land. An unnamed ephemeral drainage is located approximately 0.90 miles to the west. The nearest occupied residence is approximately 0.30 miles to the west of the wellhead. There are no groundwater extraction wells located within 0.25 miles of the site. Depth to groundwater is unknown but expected to be encountered at a depth of approximately 95 feet below ground surface (bgs) based on DWR records of a residential well drilled in 2004 in place 0.31 miles west of the site. There are no additional sensitive areas, floodplains, wetlands, or wildlife habitats identified within a quarter mile of the facility. See the attached Figure 1 for an illustration of the location of the Site.

SITE INVESTIGATION PLAN

TYPE OF WASTE:

- ☒ E&P Waste ☐ Other E&P Waste ☐ Non-E&P Waste
- ☒ Produced Water ☐ Workover Fluids
- ☒ Oil ☐ Tank Bottoms
- ☒ Condensate ☐ Pigging Waste
- ☐ Drilling Fluids ☐ Rig Wash
- ☐ Drill Cuttings ☐ Spent Filters
- ☐ Pit Bottoms
- ☐ Other (as described by EPA)

DESCRIPTION OF IMPACT

Impacted?	Impacted Media	Extent of Impact	How Determined
UNDETERMINED	SOILS	Unknown	Not yet determined

INITIAL ACTION SUMMARY

Description of initial action or emergency response measures take to abate, investigate, and/or remediate impacts associated with E&P Waste.

Great Western proposes to conduct closure of the Grant Properties 1 tank battery, wellhead, and on-location flowlines. P&A of the well is scheduled to commence on 4/4/22 and be completed by 4/8/22. Tank battery closure, wellhead cut and cap, and flowline removal activities are planned to commence on 4/14/22 and be completed by 6/17/22. Great Western will conduct site investigation activities, field screening, and confirmation soil sampling activities during closure in accordance with COGCC 900 Series Rules. Discrete soil samples will be collected and analyzed pursuant to Rule 915 following the general sample collection guidance in Rule 915.e.(2). All waste generated during the closure activities will be managed and disposed of at a licensed disposal facility in accordance with Rules 905 and 906.

PROPOSED SAMPLING PLAN

Proposed Soil Sampling

- ☒ Will soil samples be collected as part of this investigation? (Number, type (grab/composite), analyses, and locations of samples):

During tank battery closure, at least 15 discrete soil samples will be collected for field screening only and at least 4 discrete soil samples will be collected for laboratory analysis of benzene, toluene, ethylbenzene, total xylenes (BTEX), naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene and gasoline range organics (GRO) [C6-C10] by EPA Method 8260 and for diesel range organics (DRO) [C10-C28] and residual range organics (RRO) [C28-C40] by EPA Method 8015. Analytical results for GRO, DRO, and RRO will be added together to calculate total petroleum hydrocarbons (TPH). In addition, a soil sample will be collected from the base of the partially buried produced water vessel and will be analyzed for the Soil Suitability for Reclamation Parameters; Electrical Conductivity (EC), Sodium Absorption Ratio (SAR), and pH by Saturated Paste Method, and boron by Hot Water-Soluble Soil Extract Method. See the Additional Investigative Actions section below for further discussion.

Proposed Groundwater Sampling

- ☒ Will groundwater samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Depth to groundwater is unknown but is anticipated to be at least 95 feet bgs based on the static water level reported in the nearest DWR permitted well. If a pathway to groundwater is encountered during closure activities, a groundwater sample will be collected in accordance with COGCC Rule 915.e.(3) and will be submitted to an accredited laboratory for analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, and 1,3,5-trimethylbenzene by EPA Method 8260. If groundwater is encountered in the wellhead excavation, a groundwater sample will be collected and analyzed using the same methods described above.

Proposed Surface Water Sampling

- ☐ Will surface water samples be collected as part of this investigation? (Number, analyses, and locations of samples):

Additional Investigative Actions

- ☐ Additional alternative investigative actions described in attached Site Investigation Plan (summary):

Five discrete soil samples will be collected for field screening at the wellhead excavation. The sample collected from the floor of the wellhead excavation will be submitted for laboratory analysis of BTEX, naphthalene, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene and GRO, DRO, and RRO by the methods discussed above. One sidewall sample will be collected from the wellhead excavation and analyzed for the Soil Suitability for Reclamation parameters by the same methods discussed above.

See the attached Figures 2 and 3 for an illustration of the Site layout and proposed discrete soil sample locations for field screening and laboratory analysis. See the Operator Comments Section in the Submit Tab for further discussion regarding proposed soil sampling activities.

SITE INVESTIGATION REPORT

SAMPLE SUMMARY

Soil

Number of soil samples collected _____ 0

Number of soil samples exceeding 915-1 _____

Was the areal and vertical extent of soil contamination delineated? _____

Approximate areal extent (square feet) _____

NA / ND

_____ Highest concentration of TPH (mg/kg) _____

_____ Highest concentration of SAR _____

_____ BTEX > 915-1 _____

_____ Vertical Extent > 915-1 (in feet) _____

Groundwater

Number of groundwater samples collected _____ 0

Was extent of groundwater contaminated delineated? No _____

Depth to groundwater (below ground surface, in feet) _____

Number of groundwater monitoring wells installed _____

Number of groundwater samples exceeding 915-1 _____

_____ Highest concentration of Benzene (µg/l) _____

_____ Highest concentration of Toluene (µg/l) _____

_____ Highest concentration of Ethylbenzene (µg/l) _____

_____ Highest concentration of Xylene (µg/l) _____

_____ Highest concentration of Methane (mg/l) _____

Surface Water

_____ 0 Number of surface water samples collected

_____ Number of surface water samples exceeding 915-1

If surface water is impacted, other agency notification may be required.

OTHER INVESTIGATION INFORMATION

☐ Were impacts to adjacent property or offsite impacts identified?

☐ Were background samples collected as part of this site investigation?

☐ Was investigation derived waste (IDW) generated as part of this investigation?

Volume of solid waste (cubic yards) _____

Volume of liquid waste (barrels) _____

☐ Is further site investigation required?

REMEDIAL ACTION PLAN

SOURCE REMOVAL SUMMARY

Describe how source is to be removed.

If impacted soil is encountered, Great Western will either dig and haul impacted soils to a commercial landfill or treat impacted soils above COGCC Table 915-1 concentration levels onsite.

REMEDIATION SUMMARY

Describe how remediation of existing impacts to soil and groundwater is to be accomplished (i.e. summarize remedial action plan). Provide a brief narrative description including: technical justification, schedule for implementation, estimated time to attain NFA status, plus plans and specifications for the selected remedial action technology.

A remediation or closure plan will be developed based on the results of the confirmation soil samples collected during facility closure activities.

Soil Remediation Summary

☐ In Situ

☐ Ex Situ

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

_____ Excavate and offsite disposal
_____ If Yes: Estimated Volume (Cubic Yards) _____
_____ Name of Licensed Disposal Facility or COGCC Facility ID # _____
_____ Excavate and onsite remediation
_____ Land Treatment
_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Other _____

Groundwater Remediation Summary

_____ Bioremediation (or enhanced bioremediation)
_____ Chemical oxidation
_____ Air sparge / Soil vapor extraction
_____ Natural Attenuation
_____ Other _____

GROUNDWATER MONITORING

If groundwater has been impacted, describe proposed monitoring plan, including # of wells or sample points, monitoring schedule, analytical methods, points of compliance. Attach a groundwater monitoring location diagram.

REMEDATION PROGRESS UPDATE

PERIODIC REPORTING

Approved Reporting Schedule:

☐ Quarterly☐ Semi-Annually☐ Annually☐ Other

☐ Request Alternative Reporting Schedule:

☐ Semi-Annually☐ Annually☐ Other

Rule 913.e:

After initial approval of a Form 27, the Operator will provide quarterly update reports in a Supplemental Form 27 to document progress of site investigation and remediation, unless an alternative reporting schedule has been requested by the Operator and approved by the Director. The Director may request a more frequent reporting schedule based on site-specific conditions.

Report Type:

☐ Groundwater Monitoring☐ Land Treatment Progress Report☐ O&M Report☐ Other

WASTE DISPOSAL INFORMATION

Was E&P waste generated as part of this remediation?

Describe beneficial use, if any, of E&P Waste derived from this remediation project:

Volume of E&P Waste (solid) in cubic yards

E&P waste (solid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

Volume of E&P Waste (liquid) in barrels

E&P waste (liquid) description

COGCC Disposal Facility ID #, if applicable:

Non-COGCC Disposal Facility:

RECLAMATION PLAN

RECLAMATION PLANNING

Describe reclamation plan. Discuss existing and new grade recontouring; method and testing of compaction alleviation; and reseeding program, including location of new seed, seed mix and noxious weed prevention. Attach diagram or drawing.

If necessary, the site will be reclaimed in accordance with COGCC 1000-Series Rules.

Is the described reclamation complete?

Does the reclamation described herein constitute interim or final reclamation of the Oil and Gas Location?

☐ Interim☐ Final

Did the Surface Owner provide the seed mix?

If YES, does the seed mix comply with local soil conservation district recommendations?

Did the local soil conservation district provide the seed mix?

SITE RECLAMATION DATES

Proposed date of commencement of Reclamation.

Proposed date of completion of Reclamation.

IMPLEMENTATION SCHEDULE

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

PRIOR DATES

Date of Surface Owner notification/consultation, if required. 03/14/2022

Actual Spill or Release date, or date of discovery. _____

SITE INVESTIGATION DATES

Date of Initial Actions described in Site Investigation Plan (start date). 04/04/2022

Proposed site investigation commencement. 04/14/2022

Proposed completion of site investigation. _____

REMEDIAL ACTION DATES

Proposed start date of Remediation. _____

Proposed date of completion of Remediation. _____

Per Rule 913.d.(2): Any change from the approved implementation schedule will be requested at least 14 days in advance, and the Operator may not make the change without the Director's approval.

☐ Change from approved implementation schedule per Rule 913.d.(2).

Basis for change in implementation schedule:

OPERATOR COMMENT

Great Western will remove the 69-foot flowline by cutting it into sections and pulling the sections from the subsurface. A minimum of 2 discrete soil samples will be collected for field screening during flowline abandonment. If indications of soil impacts are present, the samples will be submitted to an accredited laboratory for analyses as discussed in the Proposed Soil Sampling section under the Site Investigation Plan tab. If indications of groundwater impacts are present, samples will be collected and submitted to an accredited laboratory for analyses as discussed in the Proposed Groundwater Sampling section under the Site Investigation Plan tab.

Follow-up reporting will be submitted via a Form 27 Supplemental within 90 days after work is completed.

I hereby certify all statements made in this form are to the best of my knowledge true, correct, and complete.

Signed: Jason Davidson

Title: Senior EHS Specialist

Submit Date: 03/17/2022

Email: jdavidson@gwp.com

Based on the information provided herein, this Application for Site Investigation and Remediation Workplan complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: CHRIS CANFIELD

Date: 03/21/2022

Remediation Project Number: 22476

Condition of Approval

COA Type

Description

0 COA

Attachment Check List

Upon approval, the approved Form 27 and all listed attachments will be indexed to the Remediation Project file. Only the approved Form 27 will also be indexed to the related Facilities.

<u>Att Doc Num</u>	<u>Name</u>
402988012	FORM 27-INICIAL-SUBMITTED
402988020	MAP

Total Attach: 2 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)