

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC NAUGLE-66S95W /25NENE

Location ID: 335106



Photo #6220 from entrance to location.



Photo #6221 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC NAUGLE-66S95W /25NENE

Location ID: 335106



Photo #6224 Stored equipment and supplies.



Photo #6226 Stored equipment and supplies.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC NAUGLE-66S95W /25NENE

Location ID: 335106



Photo #6222 Location lacks stabilization.



Photo #6225 Insufficient tracking controls at entrance to location.