

Inspection Photos

API: 071-09236

Operator: OGRIS OPERATING LLC

Inspection Date: 3/18/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09236 | Date: 3/18/2022

Inspection Photos



Photo 1. Facing toward the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/18/2022

Inspection Photos



Photo 2. There is oily fluids in the engine skid and spill onto the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09236 | Date: 3/18/2022