

Inspection Photos

API: 071-07901

Operator: OGRIS OPERATING LLC

Inspection Date: 3/18/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07901 | Date: 3/18/2022

Inspection Photos



Photo 1. Facing southwest toward the wellsite. The vegetation is well established at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07901 | Date: 3/18/2022

Inspection Photos



Photo 2. Maintenance has been performed on muffler to reduce the noise.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07901 | Date: 3/18/2022