

Inspection Photos
Location Name: Horsetail 30H PAD
Location ID: 445579



Photo 1 – Signs at Entrance

Photo 2 – 3116 Wellhead

Inspection Photos
Location Name: Horsetail 30H PAD
Location ID: 445579



Photo 3 – Wellheads

Photo 4 – 1948 Wellhead – Sign Missing

Inspection Photos
Location Name: Horsetail 30H PAD
Location ID: 445579



Photo 5 – 1947 Wellhead

Photo 6 – Gas Meter Shed