

Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 1 – Stained Soil at Wellhead



Photo 2 – Stained Soil at Wellhead

Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 3 – Stained Soil at Wellhead



Photo 4 – Stained Soil at Exhaust



Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 5 – ECD and Flare



Photo 6 – Heater Treater



Inspection Photos
Location Name: Razor 14-1143H
Location ID: 430061



Photo 7 – Tank Battery



Photo 8 – Tank Battery Sign

