

# Inspection Photos

March 15, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335548

Location Name: Weinreis A Pad

Inspection Document #: 702800039

Garfield County, CO

SWNW Section 16 T6S R92W

Anna O'Malley  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 1.** Photo taken from the entrance to the Location facing east shows an overview of the Location.

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 2.** Photo taken from the northern interim areas shows undesirable plant species/weed debris accumulating on the Location.



**Photo 3.** Photo taken from the southeast of the Location facing north shows undesirable plant species/weed debris accumulating in Production areas.



Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 4.** Photo taken from the southeast of the Location facing northwest shows undesirable plant species/weed debris accumulating in Production areas.



**Photo 5.** Photo shows undesirable plant species/weed debris accumulating around production equipment.



Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 6.** Photo taken from the well area shows storage of unnecessary equipment on Location.

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 7.** Photo taken from the entrance of the Location facing northeast shows rutting occurring on the pad.

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 8.** Photo taken from the east of the Location facing south shows unstabilized cut slopes.



**Photo 9.** Photo taken from the east of the Location shows rill erosion occurring on the unstabilized cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800039

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 10.** Photo taken from east of the Location shows rill erosion occurring on the unstabilized cut slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800039

Inspection Photos  
Location Name: Weinreis A Pad  
Location ID: 335548



**Photo 11.** Photo taken from the northern interim areas of the Location shows interim areas colonized by annual weeds and dominated by bare ground.



**Photo 12.** Refer to Photo 11 comments.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Number: 702800039