

Final Reclamation Inspection

March 14, 2022

Operator: KERR MCGEE OIL & GAS ONSHORE LP #47120

Location ID: 328259

Inspection Document #: 697503818

Weld County, CO

SWSE Section 12 T3N R67W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: OPATRIL #12-15L
Location ID: 328259



Photo 1. Photo taken from the well location, facing West. Photo illustrates there is some desirable vegetation but will remain in process.



Inspection Photos
Location Name: OPATRIL #12-15L
Location ID: 328259



Photo 2. Photo taken along the well location, facing South. See comments under Photo 1.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Number: 697503818

Inspection Photos
Location Name: OPATRIL #12-15L
Location ID: 328259



Photo 3. Photo taken from the well location access road, facing North. Access road is pre-existing prior to oil and gas. Photo illustrates the access road is stabilized.



Photo 4. 1984 aerial imagery illustrates the well location access road was pre-existing prior to oil and gas.

