

Inspection Photos
Location Name: Musser, B W "B" 18
Location ID: 312917



Photo 1. Overview of location taken facing southwest. Ruts in access road.



Photo 2. Ruts in access road.

