

Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 1 – Tank Battery Sign



Photo 2 – Production Equipment



Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 3 – Tank Battery



Photo 4 – Compressor



Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 5 – Compressor



Photo 6 – Heater Treaters



Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 7 – Flare



Photo 8 – Production Equipment

Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 9 – LACTs



Photo 10 – LACTs

Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 11 – Missing Labels – NFPA, Content and Capacity
Unmarked Risers


Photo 10 – LACTs



Inspection Photos
Location Name: Razor 25 CPB
Location ID: 444459



Photo 13 – Unmarked Risers



**Photo 14 – Missing Labels – NFPA, Content and Capacity
Unmarked Risers**

