

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 1 WH sign

Photo 2 WH, stained soil

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 3 Pump Jack

Photo 4 Prime mover, gas engine

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 5 TB sign

Photo 6 TB

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 7 Horiz. Heated Sep.

Photo 8 flow lines

Inspection Photos Location Name: Vonasek #1 Location ID: 333302




Photo 9 Gas Meter Run.

Photo 10 card indicates current calibration

Inspection Photos
Location Name: Vonasek #1
Location ID: 333302



Photo 11 Vertical Separator