

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402973919

Date Received:

03/04/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 952 ECHO LANE SUITE 480

City: HOUSTON State: TX Zip: 77024

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

David Boyer

303-994-0000

david@d90energy.com

Rikki Ross

405-921-1825

rikki@d90energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689805591

Inspection Date: 03/30/2021

FIR Submit Date: 04/12/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SANDRIDGE EXPLORATION & PRODUCTION LLC

Company Number: 10598

Address: 123 ROBERT S KERR AVE

City: OKLAHOMA CITY State: OK Zip: 73102

LOCATION - Location ID: 438250

Location Name: EVANS 0780 Number: 21 County: _____

Qtrqr: NWNE Sec: 21 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.569537 Longitude: -106.376011

FACILITY - API Number: 05-057-00 Facility ID: 438250

Facility Name: EVANS 0780 Number: 21

Qtrqr: NWNE Sec: 21 Twp: 7N Range: 80W Meridian: 6

Latitude: 40.569537 Longitude: -106.376011

CORRECTIVE ACTIONS:

1 ☒ CA# 149459

Corrective Action: Install sign to comply with Rule 605.h.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2 ☒ CA# 149460

Corrective Action: Install sign to comply with Rule 605.h.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

3 ☒ CA# 149461

Corrective Action: Install sign to comply with Rule 605.d.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

4 ☒ CA# 149462

Corrective Action: Comply with Rule 606.
Properly dispose of oily waste in accordance with 905.e.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 04/30/2021

Operator
Comment: Stained gravel removed in April of 2021.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

5 ☒ CA# 149463

Corrective Action: Sign not updated to reflect current operator.

Date: 05/12/2021

Response: CA COMPLETED

Date of Completion: 01/05/2022

Operator
Comment: D90 Energy is operator of record as of 1/5/22. Signage is accurate and complete.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Rikki Ross

Signed: _____

Title: Regulatory Analyst

Date: 3/4/2022 12:23:11 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402973919	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files