

Inspection Photos

March 24, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 335549

Location Name: Gentry B Pad

Inspection Document #: 702800065

Garfield County, CO

SENW Section 17 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Gentry B Pad
Location ID: 335549



Photo 1. Photo taken from the southeast of the Location shows undesirable plant species/weed debris accumulating in interim areas and production areas adjacent to the tank battery.



Photo 2. Photo taken from the south of the Location shows undesirable plant species/weed debris accumulating in production areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800065

Inspection Photos
Location Name: Gentry B Pad
Location ID: 335549



Photo 3. Photo shows BMPs to prevent wildlife access to the well cellars were missing or insufficient




Photo 4. Refer to Photo 3 comment.

Inspection Photos
Location Name: Gentry B Pad
Location ID: 335549



Photo 5. Photo taken from the western interim areas of the Location facing northeast shows interim areas dominated by annual, non-native and undesirable plant species/weeds including kochia, cheatgrass, mustard sp. and annual wheatgrass.



Photo 6. Photo taken from the northern interim areas of the Location facing east. Refer to additional comments under Photo 5.

Inspection Photos
Location Name: Gentry B Pad
Location ID: 335549



Photo 7. Photo taken from the south of the Location facing west shows cut slopes dominated by the undesirable plant species/weed, kochia. The perennial grass, crested wheatgrass is also present, but uncommon.



Photo 8. Photo taken from the east of the Location facing southeast shows cut slopes dominated by the undesirable plant species/weed, kochia.

