

Inspection Photos

API: 073-06615

Operator: PIONEER NATURAL RESOURCES

Inspection Date: 3/24/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 1. Drone aerial photo facing northeast toward the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 2. Facing down toward the former access road. There does not appear to be much desirable vegetation establishing. Additional reseeding should be performed where vegetation is not progressing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 3. Facing northeast along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 4. Drone aerial photo facing east toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 5. Center of the location facing southeast. There are two cows inside the fenced location. The fence will need to be checked for repair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 6. Center of the location facing northeast.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 7. Center of the location facing northwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 8. Center of the location facing southwest.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 9. Facing down toward the groundcover. There does not appear to be much desirable vegetation establishing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022

Inspection Photos



Photo 10. Drone aerial photo facing southwest toward the fenced location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06615 | Date: 3/24/2022