

Inspection Photos

API: 073-06743

Operator: K3 OIL & GAS OPERATING

Inspection Date: 3/24/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 1. Drone aerial photo facing east toward the location. The fence at the red arrow will need to be reinstalled to the original position.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 2. Drone aerial photo facing west toward the location. The vegetation has been mowed at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 3. Center of the location facing northeast. There are undesirable weeds throughout the location. Mowing has been performed but additional reseeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 4. Center of the location facing southwest. There are undesirable weeds throughout the location. Mowing has been performed but additional reseeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 5. Facing down toward the groundcover. There are undesirable weeds throughout the location. Mowing has been performed but additional reseeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022

Inspection Photos



Photo 6. Drone aerial photo facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/24/2022