

Inspection Photos

API: 073-06727

Operator: K3 OIL & GAS OPERATING

Inspection Date: 3/24/2022



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos



Photo 1. Drone aerial photo facing east toward the reclaimed portion of access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos



Photo 2. Drone aerial photo facing northeast along the former access road which.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos



Photo 3. Drone aerial photo facing northeast toward the access road. The vegetation does not appear to be establishing along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos



Photo 4. Drone aerial photo facing east toward the location. The vegetation has been mowed at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos




Photo 5. Drone aerial photo facing east toward the location. The vegetation has been mowed at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022

Inspection Photos



Photo 6. Facing down toward the groundcover. There appears to be mostly undesirable weeds throughout the location. Mowing has been performed but additional reseeding will need to be performed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06727 | Date: 3/24/2022