

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 1 WH sign

Photo 2 WH

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 3 Pump jack

Photo 4 TB sign

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 5 TB

Photo 6 Stained soil by crude tank valve

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 7 Stained soil by crude tank load out line

Photo 8 Stained soil in Separator housing

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 9 Gas Meter Run

Photo 10 card indicates current calibration

Inspection Photos
Location Name: Guildner 1
Location ID: 317889



Photo 11 Horiz. Heated Separator

Photo 12 PW vessel