

FORM
43

Rev
05/21

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

02/08/2022

Document Number:

402950351

ANALYTICAL SAMPLE DATA SUBMITTAL FORM

Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

Operator Information

OGCC Operator Number: 47120 Contact Person: Erik Mickelson
Company Name: KERR MCGEE OIL & GAS ONSHORE LP Phone: (720) 929-4306
Address: P O BOX 173779 Fax: ()
City: DENVER State: CO Zip: 80217-3779 Email: Erik_Mickelson@oxy.com

Identification Information

API Number: 05 - - OGCC Facility ID: 323420 Initial Form 19 or 27 Document number:
Facility Name: WARDELL Facility Number: 2G-19HZ Facility Type: LOCATION
Location QtrQtr: NWNE Section: 19 Township: 3N Range: 65W Meridian: 6
County: WELD Field Name: WATTENBERG
Federal, Indian or State Lease Number:

Information Submitted By:

Company Name: Absaroka Agent Name: Tanya Cude Title: Environmental Scientist
Phone Number: 352-318-4034 Email: Tanya.Cude@Absarokasolutions.com

Rule 909.J Inspection Information

Date the Pit was Inspected

On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted

Sample Location Information:

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 752922 Facility Name: Hochmiller_84411 Facility Type: Commercial
Location: QtrQtr: NWNE Sec: 32 Twp: 3N Range: 65W Meridian: 6
County Name: WELD Latitude: 40.188001 Longitude: -104.683636

Sample Information:

The following Sample Information has been reviewed by the COGCC:

Batch ID: 95337 Document Name: SIW File Name: 2021_11_09_Hochmiller 84411--A Isotech SIW
COGCC.xls
SampleType: Matrix:
Facility ID: 752922 Sample ID: 632348 Sample Name: Hochmiller 84411--A Sample Date: 11/09/2021
Collection Point: COM Matrix: WATER Pre Post: Voluntary Post drill
Project Number: Remediation Number: Complaint Number: NOAV Number:
Inspection Number: Spill Number: Laboratory: ISOTECH Lab Sample ID: 809358

Batch ID: 95335		Document Name: TB		File Name: 2021_11_09_Hochmiller 84411--A Trip Blank SGS COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 632346	Sample Name: Hochmiller 84411--A		Sample Date: 11/09/2021	
Collection Point: COM	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA38937-1		

Batch ID: 95338		Document Name: NG4		File Name: 2021_11_09_Hochmiller 84411--A Isotech NG4 COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 632350	Sample Name: Hochmiller 84411--A		Sample Date: 11/09/2021	
Collection Point: COM	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 809360		

Batch ID: 95338		Document Name: NG4		File Name: 2021_11_09_Hochmiller 84411--A Isotech NG4 COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 632349	Sample Name: Hochmiller 84411--A		Sample Date: 11/09/2021	
Collection Point: COM	Matrix: GAS	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 809360		

Batch ID: 95336		Document Name: SGS		File Name: 2021_11_09_Hochmiller 84411--A SGS COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 752922	Sample ID: 632347	Sample Name: Hochmiller 84411--A		Sample Date: 11/09/2021	
Collection Point: Stock	Matrix: WATER	Pre Post: Voluntary Post drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Accutest	Lab Sample ID: DA38935-1		

Sample Facility Attachment:

Facility ID	Attach Num	File Name	Document Name	File Type
752922	402950377	2021_11_09_Hochmiller 84411--A Isotech SIW.pdf	Analytical Laboratory Report	PDF
752922	402950374	2021_11_09_Hochmiller_84411_A_Well.jpg	Photographs	JPG
752922	402950362	2021_11_09_Hochmiller 84411--A SGS.pdf	Analytical Laboratory Report	PDF
752922	402950370	2021_11_09_Hochmiller_84411_A_PrePostPurge.jpg	Photographs	JPG
752922	402950367	2021_11_09_Hochmiller_84411_A_FS_COGCC.pdf	Field Data Report	PDF
752922	402950372	2021_11_09_Hochmiller_84411_A_Spigit.jpg	Photographs	JPG
752922	402950386	2021_11_09_Hochmiller 84411--A Isotech NG4.pdf	Analytical Laboratory Report	PDF
752922	402950357	2021_11_09_Hochmiller 84411--A Trip Blank SGS.pdf	Analytical Laboratory Report	PDF

Sample COGCC Well Related:

No Sample COGCC Well Related Information Provided.

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/29/2022
Total: 1 comment(s)		