

Inspection Photos

March 24, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 436713

Location Name: Valley Farms L Pad

Inspection Document #: 702800083

Garfield County, CO

SESE Section 11 T6S R92W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Valley Farms L Pad
Location ID: 436713



Photo 1. Photo taken from the Location entrance shows an overview of the Location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800083

Inspection Photos
Location Name: Valley Farms L Pad
Location ID: 436713




Photo 2. Photo taken from the south of the Location shows debris.



Photo 3. Refer to Photo 2 comment.



Inspection Photos
Location Name: Valley Farms L Pad
Location ID: 436713



Photo 4. Photo taken from the west of the Location facing north shows interim areas of the Location where the working pad has recently been reduced.



Photo 5. Photo taken from the south of the Location facing west shows interim areas of the Location where the working pad has recently been reduced.

Inspection Photos
Location Name: Valley Farms L Pad
Location ID: 436713



Photo 6. Photo taken from the south of the Location facing east shows cut slopes are colonized by perennial grasses and occasional shrubs.



Photo 7. Photo taken from the south of the Location facing south shows cut slopes are colonized by perennial grasses.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800083