

Inspection Photos

March 24, 2022

Operator: TEP Rocky Mountain- #96850

Location ID: 417777

Location Name: Frei A Pad

Inspection Document #: 702800088

Garfield County, CO

Lot 10 Section 7 T6S R91W

Anna O'Malley
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 1. Photo taken from the Location entrance facing south shows an overview of the Location.



Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 2. Photo taken from the well area facing south shows a dumpster and unused fence panels being stored on Location.



Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 3. Photo taken from the slopes on the east of the Location showing establishment of perennial grasses, shrubs and annual undesirable plant species/weeds.



Photo 4. Refer to Photo 3 comments.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800088

Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 5. Photo taken from the southwest of the Location facing south shows interim area slopes have been hydromulched.



Photo 6. Photo taken from the north of the Location facing west shows interim areas have been hydromulched.



Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 7. Photo taken from the eastern slopes of the Location shows rill erosion occurring.



Photo 8. Photo taken from the eastern slopes of the Location shows sediment eroding and accumulating at the base of the cut slopes.

Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 9. Photo taken from the slopes on the southeast of the Location behind the tank battery shows an overview of the eroding slope.



Photo 10. Photo taken from the slopes on the southeast of the Location behind the tank battery shows a close-up of rill erosion occurring on the slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Number: 702800088

Inspection Photos
Location Name: Frei A Pad
Location ID: 417777



Photo 11. Photo taken from the southwest of the working pad area facing northwest shows a perimeter stormwater swale which was lined with geotextile fabric and angular rip-rap.

