

**FORM  
43**Rev  
05/21**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109**OGCC RECEPTION****Receive Date:****03/17/2022****Document Number:****402800611****ANALYTICAL SAMPLE DATA SUBMITTAL FORM**Uses of the Analytical Sample Data Submittal Form:

Submission of sample facility information, water sample analytical data, gas sample analytical data, and soil sample analytical data in compliance with COGCC Rules 411.b. (5), 411.c. (5), 420, 614.c, 615, 805.D, 907.b.(9), 909.J, COGCC Policies, and Form Conditions of Approval.

**Operator Information**

OGCC Operator Number: 10459 Contact Person: Luke Kelly  
Company Name: EXTRACTION OIL & GAS INC Phone: (720) 315-8934  
Address: 370 17TH STREET SUITE 5200 Fax: ( )  
City: DENVER State: CO Zip: 80202 Email: lkelly@civiresources.com

**Identification Information**

API Number: 05 -   -   OGCC Facility ID: 456775 Initial Form 19 or 27 Document number:    
Facility Name: NORTHWEST B PAD Facility Number:   Facility Type: LOCATION  
Location QtrQtr: NENW Section: 9 Township: 1S Range: 68W Meridian: 6  
County: BROOMFIELD Field Name: WATTENBERG  
Federal, Indian or State Lease Number:

**Information Submitted By:**

Company Name: Apex Companies, LLC Agent Name: Heather Shideman Title: Project Manager  
Phone Number: 307-620-0117 Email: heather.shideman@apexcos.com

**Rule 909.J Inspection Information**Date the Pit was Inspected  On inspection the Pit was: ☐ Unlined ☐ Lined ☐ Fenced ☐ Netted**Sample Location Information:**

The following Sample Locations have been reviewed by COGCC Staff:

Facility ID: 761985 Facility Name: Grebe 137662 Facility Type: Domestic Well  
Location: QtrQtr:   Sec:   Twp:   Range:   Meridian: 6  
County Name: BROOMFIELD Latitude: 39.980296 Longitude: -105.009797

**Sample Information:**

The following Sample Information has been reviewed by the COGCC:

Batch ID: 91041 Document Name: SIW File Name: XOG\_BWSE\_GWA\_Northwest\_B\_Pad\_06-08-2021\_Grebe\_137662\_SIW\_COGCC.xls  
SampleType:   Matrix:    
Facility ID: 761985 Sample ID: 627655 Sample Name: Grebe\_137662 Sample Date: 06/08/2021  
Collection Point: Dom Matrix: WATER Pre Post: Rule 615 Pre Drill  
Project Number:   Remediation Number:   Complaint Number:   NOAV Number:    
Inspection Number:   Spill Number:   Laboratory: ISOTECH Lab Sample ID: 794759

Batch ID: 91043		Document Name: NG1		File Name: XOG_BWSE_GWA_Northwest_B_Pad_06-08-2021_Grebe_137662_NG1_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 761985	Sample ID: 627658	Sample Name: Grebe_137662		Sample Date: 06/08/2021	
Collection Point: Dom	Matrix: GAS	Pre Post: Rule 615 Pre Drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ISOTECH	Lab Sample ID: 795300		

---

Batch ID: 97357		Document Name: Summit		File Name: XOG_BWSE_GWA_Northwest_B_Pad_06-08-2021_Grebe_137662_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 761985	Sample ID: 634443	Sample Name: Grebe_137662		Sample Date: 06/08/2021	
Collection Point: Dom	Matrix: WATER	Pre Post: Rule 615 Pre Drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Summit Scientific	Lab Sample ID: 2106149-01		

---

Batch ID: 97356		Document Name: Energy		File Name: XOG_BWSE_GWA_Northwest_B_Pad_06-08-2021_Grebe_137662_Energy_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 761985	Sample ID: 634442	Sample Name: Grebe_137662		Sample Date: 06/08/2021	
Collection Point: Dom	Matrix: WATER	Pre Post: Rule 615 Pre Drill			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: ENERGYLAB	Lab Sample ID: G21060203-001A		

---

Batch ID: 91040		Document Name: Trip_Blank		File Name: XOG_BWSE_GWA_Northwest_B_Pad_06-08-2021_Grebe_137662_Trip_Blank_COGCC.xls	
SampleType: _____			Matrix: _____		
Facility ID: 761985	Sample ID: 627654	Sample Name: Grebe_137662		Sample Date: 06/08/2021	
Collection Point: TB	Matrix: WATER	Pre Post: Trip Blank			
Project Number: _____	Remediation Number: _____	Complaint Number: _____	NOAV Number: _____		
Inspection Number: _____	Spill Number: _____	Laboratory: Summit Scientific	Lab Sample ID: 2106148-01		

### Sample Facility Attachment:

No Facility Attachment

### Sample COGCC Well Related:

Sample ID	API Num	Well Name & Num	Sample Reason
627655	014-20853	NORTHWEST B S20-25-19N	Rule 615 Pre Drill
627655	014-20854	NORTHWEST B S20-25-18N	Rule 615 Pre Drill
627658	014-20853	NORTHWEST B S20-25-19N	Rule 615 Pre Drill
627658	014-20854	NORTHWEST B S20-25-18N	Rule 615 Pre Drill
634442	014-20853	NORTHWEST B S20-25-19N	Rule 615 Pre Drill
634442	014-20854	NORTHWEST B S20-25-18N	Rule 615 Pre Drill
634443	014-20853	NORTHWEST B S20-25-19N	Rule 615 Pre Drill
634443	014-20854	NORTHWEST B S20-25-18N	Rule 615 Pre Drill

### General Comments

User Group	Comment	Comment Date
Environmental	The data submitted by the operator can be accessed through the COGIS data system.	03/30/2022
Environmental	Returned to Draft for correction.	03/17/2022
Total: 2 comment(s)		