

# Inspection Photos

API: 071-09057

Operator: WAPITI OPERATING LLC

Inspection Date: 3/29/2022



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-09057 | Date: 3/29/2022

## Inspection Photos



**Photo 1.** There is stormwater pooling on the road causing vehicle rutting and widening of the road. This area needs to be repaired and stabilized. Approx. Lat/Long:37.02629,-104.85264.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09057 | Date: 3/29/2022



## Inspection Photos



**Photo 2.** Facing northeast toward the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-09057 | Date: 3/29/2022