

Inspection Photos

03/28/2022

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335880

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335880



March 28, 2022
39.56533016N 108.17908435W

Photo 1: Photo shows pump trailer stored on the west end of the battery facility. Photo also shows stormwater ponding around equipment.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335880



Photo 2: Photo of pump trailer and stormwater; liner/secondary containment BMP at pump inadequate to prevent spills and contamination of stormwater. Stained soils around pump equipment/liner evident.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC - 10456
Location ID: 335880



Photo 3: Photo taken from beneath pump trailer. Photo shows leaks/drips and impacting stormwater

