

## Turner Securities A 1

Inspection Doc #693903899 CA Complete 03/18/22

Removed multiple loads of trash and debris that had been dumped over the edge of location. Installed a 3-wire fence and gate to identify well pad location.

