

Final Reclamation Inspection

March 25, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306404

Inspection Document #: 697503836

Weld County, CO

SESE Section 34 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: GROVES #44-34
Location ID: 306404



Photo 1. Photo taken from the well location, facing East. Photo illustrates Operator has performed final reclamation activities at the well location with the evidence of drill rows and straw crimped mulch. The well location has an open Remediation Project #17069. Photo illustrates one of the monitoring wells.

Inspection Photos
Location Name: GROVES #44-34
Location ID: 306404



Photo 2. Photo taken from the well location, facing North. See comments under Photo 1.

Inspection Photos
Location Name: GROVES #44-34
Location ID: 306404



Photo 3. Photo taken from the well location, facing West. See comments under Photo 1. Note- the access road was pre-existing prior to the development of the location.

Inspection Photos
Location Name: GROVES #44-34
Location ID: 306404



Photo 4. Photo taken from the well location, facing South. See comments under Photo 1.