

Final Reclamation Inspection

March 25, 2022

Operator: PDC ENERGY INC - 69175

Location ID: 306398

Inspection Document #: 697503838

Weld County, CO

SWSE Section 34 T7N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: GROVES #34-34
Location ID: 306398



Photo 1. Photo taken from the well location, facing South. Photo illustrates Operator has performed final reclamation activities at the well location with the evidence of drill rows and straw crimped mulch. The well location has an open Remediation Project #17550.