

Inspection Photos
Location Name: Winder Pad
Location ID: 430438




Photo 1: Wellhead Sign



Photo 2: Stained soil



Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Photo 3: Wellhead Sign




Photo 4: Stained soil

Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Photo 5: Stained soil



Photo 6: Wellhead Sign

Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Colorado Oil & Gas Conservation Commission
40.5065, -104.89129, 1464.8m, 66°
Mar 30, 2022 10:33:15 AM

Photo 7: Stained soil removed



Colorado Oil & Gas Conservation Commission
40.50642, -104.8913, 1465.1m, 64°
Mar 30, 2022 10:33:32 AM

Photo 8: Wellhead Sign



Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Photo 9: Stained Soil removed



Photo 10: Wellhead Sign

Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Photo 11: Stained soil removed



Photo 12: Wellhead Sign

Inspection Photos
Location Name: Winder Pad
Location ID: 430438



Photo 13: Stained soil