

**WHP Misty 2-7 Pit Closure Photos**

1/20/2022  
Before pit closure  
At SW corner of pit looking north



1/20/2022  
Before pit closure  
At north side of pit looking south



1/20/2022

Before pit closure

At NW corner of pit looking SE



1/21/2022

Redistributed, sloped & compacted cuttings

At north side of pit looking south



1/22/2022

Starting pit backfill operations

At NE corner of pit looking south



1/22/2022

Starting pit backfill operations

At west side of pit looking east



1/24/2022

Pit backfill operations

At NW corner of pit looking SE



1/24/2022


Pit backfill operations

At NW corner of pit looking south



1/24/2022

After pit closure complete  
At east side of pit looking west



1/24/2022

After pit closure complete  
At entrance on east side of pad looking west



1/24/2022

After pit closure complete

At entrance on east side of pad looking west

