

Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889



Photo 1 WH sign.

Photo 2 WH

Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889



Photo 3 TB sign.

Photo 4 TB



Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889




Photo 5 LACT

Photo 6 Compressor

Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889



Photo 7 VRU

Photo 8 Horiz. Heated Separators



Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889



Photo 9 ECD

Photo 10 VRT

Inspection Photos
Location Name: Scott 27N-32HZ
Location ID: 435889



Photo 11 Gas Meter Run