

**Inspection Photos**  
**Location Name: C Lisco 14-32**  
**Location ID: 320063**



**Photo #1 Tanks.**



**Photo #2 Open top tank (fluid in tank is less then 2 foot from the top).**

Inspection Photos  
Location Name: C Lisco 14-32  
Location ID: 320063



**Photo #3 Separator and compressor house.**



**Photo #4 weeds around separator**

Inspection Photos  
Location Name: C Lisco 14-32  
Location ID: 320063



Photo #5 weeds and trash.



Photo #6 well head house.

**Inspection Photos**  
**Location Name: C Lisco 14-32**  
**Location ID: 320063**



**Photo # 7 Well head.**



**Photo #8 trash in well head house.**

**Inspection Photos**  
**Location Name: C Lisco 14-32**  
**Location ID: 320063**



**Photo #9 trash in compressor house.**



**Photo #10 old valve leaking in well head house.**