

**Inspection Photos**  
**Location Name: Jacks Draw Unit 3**  
**Location ID: 312824**



**Photo 1. Overview of location taken facing south. Ruts on location.**

**Inspection Photos**  
**Location Name: Jacks Draw Unit 3**  
**Location ID: 312824**



**Photo 2. No secondary containment.**



**Photo 3. Ruts on location.**