

Inspection Photos
Location Name: Jacks Draw Unit 20
Location ID: 416378



Photo 1. Overview of location taken facing north. Ruts on location.



Inspection Photos
Location Name: Jacks Draw Unit 20
Location ID: 416378



Photo 2. Ruts on access road.



Photo 3. Ruts on location.

