

Inspection Photos
Location Name: Jacks Draw Unit 2
Location ID: 312816



Photo 1. Overview of location taken facing east.



Photo 2. Ruts on location.

