

Inspection Photos
Location Name: Jacks Draw Unit No. 17
Location ID: 313098



Photo 1. Overview of location taken facing east.



Photo 2. Ruts on location.

Inspection Photos
Location Name: Jacks Draw Unit No. 17
Location ID: 313098



Photo 3. Sediment migrating down access road.



Photo 4. Sediment migrating down and off access road.

Inspection Photos
Location Name: Jacks Draw Unit No. 17
Location ID: 313098



Photo 5. Sediment leaving access road.



Photo 6. Sediment migrating off access road.

