

Inspection Photos
Location Name: Carl Allen 41
Location ID: 421618



Photo 1. Overview of location taken facing southeast.



Photo 2. Ruts on location.



Inspection Photos
Location Name: Carl Allen 41
Location ID: 421618



Photo 3. Sediment migration off access road.



Photo 4. Sediment migration off access road.