

Inspection Photos
Location Name: Jacks Draw Unit 9
Location ID: 312870



Photo 1. Overview of location taken facing north.



Photo 2. Ruts on location.

