

Comment: Well head is wet and stained. A puddle of fluid within the wooden cellar was observed during this inspection.

Action Taken: Dug up contaminated soil and disposed of it at the yard. Cleaned wellhead



Comment: Stand for lube oil container is wet and stained. Soil beneath stand is wet and stained.

Action Taken: Dug up contaminated soil and disposed of it at the yard. Cleaned the skid



Comment: The concrete pad and soil beneath the prime mover are wet and stained.

Action Taken: Dug up contaminated soil and disposed of it at the yard. Cleaned the skid.

