

Inspection Photos  
Operator: Simcoe  
API: 067-07767  
Date: 3/21/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southwestern project area from the western edge facing southeastward. Revegetation is progressing with sand dropseed, rubber rabbitbrush, and western wheatgrass.



Photo 4. View of the northwestern project area from the western edge facing northward.



Photo 4. View of reference area comprised of cottonwood riparian and rubber rabbitbrush shrubland with mixed grasses such as sand dropseed and smooth brome in the understory.