

Inspection Photos
Operator: Logos Operating
API: 067-05775
Date: 3/21/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northwestern project area from the western edge facing northward. Revegetation is progressing with dense rubber rabbitbrush, sand dropseed, and western wheatgrass.



Photo 3. View of reference area comprised of cottonwood riparian and rubber rabbitbrush shrubland with mixed grasses such as sand dropseed and smooth brome in the understory.