

Inspection Photos
Location Name: Bondad 33-9 #22A
API: 05-067-08138



Bondad 33-9 #22A well head.



Bondad 33-9 #22A production equipment and location of excavation for REM #19542.

Inspection Photos
Location Name: Bondad 33-9 #22A
API: 05-067-08138



Excavation to collect samples for REM #19542.



Stockpiled material next to excavation. Material in the foreground is freshly excavated, backfill material in background.

Inspection Photos
Location Name: Bondad 33-9 #22A
API: 05-067-08138



Pin flags marking sample collection points. A fourth flag is near the operator in this photo.



Three discrete samples collected from the west wall and one collected from the base of the excavation.