

TEP
BCU 23-22-198
Location # 316569



location



location/lack of battery signage

TEP
BCU 23-22-198
Location # 316569



location



location



TEP
BCU 23-22-198
Location # 316569



Chemical tank containment full of fluid



Lack of stabilization/compaction/erosion



TEP
BCU 23-22-198
Location # 316569



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion



TEP
BCU 23-22-198
Location # 316569



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion



TEP
BCU 23-22-198
Location # 316569



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction



TEP
BCU 23-22-198
Location # 316569



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion



TEP
BCU 23-22-198
Location # 316569



Lack of stabilization/compaction/erosion



Lack of stabilization/compaction/erosion

