

Inspection Photos
Operator: Simcoe
API: 067-06666
Date: 3/28/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as smooth brome, and crested wheatgrass.



Photo 3. View of the southern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of irrigated grass field with smooth brome and western wheatgrass observed.