

Inspection Photos
Operator: Simcoe
API: 067-06043
Date: 3/28/2022



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with grasses such as western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of area in the southwestern project area where bare/sparse soils need revegetation. Only scattered grasses observed here, vegetation is mostly Russian thistle.



Photo 4. View of reference area comprised of sagebrush shrubland with understory of grasses such as sand dropseed, western wheatgrass, and blue grama.