





TANK BATTERY DECOMMISSIONING FORM


SITE NAME: LIND 23-15 TANK BATTERY							DATE: 3/15/2022	REM. PROJECT #:		WEATHER: Clear 50's	
SITE DIRECTIONS: CR23 & CR80, W 0.2 mi, N and immediate W							CLIENT: Bayswater				
LEGALS AND LAT/LONG: 40.566450, -104.854269							TASMAN PERSONNEL: Justin Covey				
SOIL TYPES: Silty Sand - SM							SURFACE GRADIENT: South				
SOIL SAMPLING							FACILITY INFRASTRUCTURE				
Date/Time	Soil Sample ID	PID (ppm)	Visual	Olfactory	Photo?	Grab or Lab Sample?	EQUIPMENT		Quantity		
							Above Ground Storage Tank (AST)		2		
3/15/2022 09:49	AST-B01@3"	2.6	No Staining	No Odor	Yes	Lab	Buried or Partially Buried Vessel		1		
3/15/2022 09:54	AST-B02@3"	2.8	No Staining	No Odor	Yes	Lab	Separator		2		
3/15/2022 10:01	PW-B01@6'	4.4	No Staining	No Odor	Yes	Lab	Emission Control Device (ECD)		2		
3/15/2022 10:10	PW-N01@3'	2.9	No Staining	No Odor	Yes	Lab	Dump Line		2		
3/15/2022 10:18	PW-S01@3'	2.9	No Staining	No Odor	Yes	N/A	Wellhead		0		
3/15/2022 10:25	PW-E01@3'	2.7	No Staining	No Odor	Yes	N/A	Flowline		0		
3/15/2022 10:35	PW-W01@3'	2.8	No Staining	No Odor	Yes	N/A	Other:				
3/15/2022 10:40	DL-B01@3'	9.9	No Staining	No Odor	Yes	N/A	Soil Loads Removed				
3/15/2022 10:44	DL-B02@3'	38.2	No Staining	Slight HC Odor	Yes	Lab	IMPACTED SOIL IDENTIFIED?				
3/15/2022 10:48	SEP-B01@3"	3.2	No Staining	No Odor	Yes	Lab	ESTIMATED VOLUME OF IMPACTS:				
3/15/2022 10:50	SEP-B02@3"	4.1	No Staining	No Odor	Yes	Lab	Date		Number	CY	
3/15/2022 10:52	ECD-B01@3"	3.0	No Staining	No Odor	Yes	N/A					
3/15/2022 10:59	ECD-B02@3"	3.1	No Staining	No Odor	Yes	N/A					
3/15/2022 13:31	TB-BG01@3"	4.4	No Staining	No Odor	Yes	Lab					
3/15/2022 13:32	TB-BG01@3'	4.6	No Staining	No Odor	Yes	Lab					
3/15/2022 13:33	TB-BG01@6'	4.3	No Staining	No Odor	Yes	Lab	Total Removed		0	0	
							Disposal Facility:				
							Groundwater Recovery				
							DATE GW ENCOUNTERED:		DEPTH:		
							GROUNDWATER IN CONTACT WITH IMPACTED SOIL?				
							LNAPL OR SHEEN OBSERVED ON GW?				
GROUNDWATER SAMPLING							Date		BBLS		
Date/Time	Groundwater Sample ID	Depth Collected	Turbid?	Sheen?	Odor?	Photo?					
							Total Removed		0		
							Disposal Facility:				



Photographic Log



							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log



Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:		Volume:		Material:		Volume:	
Contents:				Contents:			
Notes/Conditions:				Notes/Conditions:			

Photographic Log

							
Equipment ID:		Equipment Type:		Equipment ID:		Equipment Type:	
Material:	Volume:	Contents:		Material:	Volume:	Contents:	
Notes/Conditions:				Notes/Conditions:			