

Inspection Photos

4/04/2022

Operator: GUNNISON ENERGY LLC - 10515

Location ID: 324459

Gunnison County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324459



Photo 1: Limited visibility due to snow cover prevented Reclamation specialist from conducting an accurate assessment of compliance with Rule 1003, 1002.f and 912. A followup inspection will be conducted. Photo shows vehicles not necessary for production have been removed from the Location.

Inspection Photos
Operator Name: GUNNISON ENERGY LLC - 10515
Location ID: 324459



Photo 2: 9/2021 Google Earth aerial image. Photo shows overview of the Location, vehicles stored on the production and interim areas, which resulted in additional degradation and disturbance.

