

Inspection Photos
Location Name: Argenta 34-10 #34-3
API: 05-067-08640



Argenta 34-10 #34-3 production equipment.



Argenta 34-10 #34-3 pump jack.

Inspection Photos
Location Name: Argenta 34-10 #34-3
API: 05-067-08640



Well head and surrounding area are stained and wet.



Lube oil container on secondary containment.