

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 1 WH sign faded and will need to be replaced in the near future.**

**Photo 2 WH.**

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 3 ancillary equip.**

**Photo 4 pump jack.**

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 5 TB sign.**

**Photo 6 TB.**

**Inspection Photos**  
**Location Name: Amoco Energy Smits Unit C1**  
**Location ID: 311287**



**Photo 7 Gas Meter Run.**

**Photo 8 Horiz. Heated Sep.**